## Oil Field Environmental Incident Summary

**Date/Time of Notice:** 02/10/2015 14:56 Incident: 20150210145612 Responsible Party: Landntech Enterprises, LLC LANDTECH ENTERPRISES, LLC Well Name: Elk Truck Unloading facility Field Name: Well File #: Date Incident: 2/7/2015 Time Incident: 15:00 Facility ID Number: Qtr: SW SW **MCKENZIE** *Twp:* 151 **Rna:** 101 **Sec:** 5 County: Location Description: Submitted By: Kirk R Johnson Received By: Contact Person: Kirk R. Johnson P.O. Box 1560 - 856 Cambrian Lane Sidney, MT 59270 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil 2000 Feet Distance Nearest Occupied Building: 2000 Feet Distance Nearest Water Well: Type of Incident: Tank Overflow Release Contained in Dike: Yes - On Facility Site Reported to NRC: No Spilled Units Recovered Units Followup **Units** 8 Barrels Oil **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: None Areal Extent:

## Potential Environmental Impacts:

None

## Action Taken or Planned:

Fluid was contained within the steel containment on location. When the weather warms up, hot fresh water will be used to rinse the oily fluid to vac trucks. The tanks will be steam cleaned & the contaminated soil removed.

Wastes Disposal Location: The Nuverra Treatment Center

Agencies Involved: Richard Ryan, NDIC Inspector

## **Updates**

Date: 2/10/2015 Status: Reviewed - Assigned to Other Agency Author: Espe, Brady

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.